1st & final bill

**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

Serial No. .....

Name of work ..... From ..... To ..... 63801

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc. of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Name of work:- Providing cc Camera at Garbage Mock Sports in ward No-15. | | | | | | |
| | Estimate cost:- RS10.00 lakhs | | | | | | |
| | Job Code : 015-17-000033 | | | | | | |
| | P-Code :- 3110 | | | | | | |
| | Work Order No:- EE/DD/WO/103/17-18 Date: 06/12/17 | | | | | | |
| | AS No :- EE/DD/AS/104/17-18, Date : 21/09/2017 | | | | | | |
| | TS No :- EE/DD/TS/50/17-18 . Date 21/09/2017 | | | | | | |
| | Recorded on:- 02/03/2018. | | | | | | |
| | Agency :- Sri. Naveen. T | | | | | | |

# MEASUREMENT BOOK

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Item No 1:- Supplying of Hikvision 8Channel NVR/DVR. DS7608NI-E1 (NVR default without HDD). Complete as per the direction of Engineer in charge of the Work | | | | | | |
| | 1) Near Kaalikamba temple | 1 | | | | 1 | |
| | 2) Near Bridge S. Ramesh Road | 1 | | | | 1 | |
| | 3) Kempegowda Nagar arch entrance | 1 | | | | 1 | |
| | 4) Near Basavamma temple | 1 | | | | 1 | |
| | 5) Near Nilamahesh waramma temple | 1 | | | | 1 | |
| | 6) Dasarahalli metro black side | 1 | | | | 1 | |
| | Total => 6 Nos. | | | | | | |

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬೆಂಗಳೂರು, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Work Order No:
Ward No-15

**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

63806

Reference to last Measurement 8

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc, of work | Number | Dimensions | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Near Nilamahistheswaramma temple | 1 - | | | | 1 | Road work ward no-15 |
| | @ Kaberahalli metro back side | 1 - | | | | 1 | |
| | | | | | Total | 6 Nos | Estimate |
| | | @ Rs 10000.00/ No | | | | | |
| | Item No 9: outdoor Substation CA06/CA05 calling, laying charges complete as per the direction in charge of the work. | 1 - | 1100.00 | | | 1100.00 mts | |
| | | | | | | 1100.00 mts | |

54000.00/-

ung/LG/PHILIPS/

work

# MEASUREMENT BOOK

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | | @ Rs. | 140.00 / mtr | | | ——— | 154000.00 /- |
| | Item No-10 : Fabricating, supplying & mounting ms box made out of SWG suitable for flat / wall mounting complete fully weather proof with provision for better heat dissipation, provided with hinged front cover, developed with lumps proof. locking arrangements with suitable size cd lamps with necessary cable entry. pipe with approved colour enamelled metal paint etc. complete b) 16 SWG complete as per the direction of Engineer in charge of the work. | 1 | 10.00 | 15400 | | 154000.00 Sqm | (carried to work Item No-15) |
| | | | | | → | 154000.00 Sqm | |
| | | @ Rs | 0.33 / Sqm | | | ——— | 50820.00 /- |
| | | | | | Total bill amt → | | 997320.00 /- |

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

63807

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Certificate:<br>1) Work done is Satisfactory.<br>2) There are No departmental issues made to the Contractor.<br>3) the Contractor has cleared all debris from work spot. | | | | | | Lumpsum work<br>Ward No-15 |

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು